



Product Care Tips

T-Shirts: Wash cold, do not bleach, tumble dry medium, remove promptly

Jackets/Coats: Wash warm, do not bleach, tumble dry medium, remove promptly

Jeans/Shorts: Wash cold, do not bleach, tumble dry medium, remove promptly

Woven Shirts: Wash cold, do not bleach, tumble dry medium, remove promptly

Base Layer: Wash cold, do not bleach, tumble dry medium, remove promptly

Bib Overalls: Wash warm, do not bleach, tumble dry medium, remove promptly

Coveralls: Wash cold, do not bleach, tumble dry with no heat or hang to dry, remove promptly

Caps: Hand wash cold, do not bleach

Gloves: Spot wash by hand in warm water with mild detergent, hang to dry. Do not use hot water, do not put in dryer.

FR Clothing: Refer to TekSolv's "How to Care for FR Garments" document.

**ALWAYS CONSULT THE GARMENT MANUFACTURER FOR
DETAILED INSTRUCTIONS AND PRECAUTIONS.**